

# **SDMS US EPA REGION V -1**

**SOME IMAGES WITHIN THIS  
DOCUMENT MAY BE ILLEGIBLE  
DUE TO BAD SOURCE  
DOCUMENTS.**



State of Illinois

# ENVIRONMENTAL PROTECTION AGENCY


Mary A. Gade, Director

2200 Churchill Road, Springfield, IL 62794-9276

217/782-6761

April 6, 1993

Cerro Copper Products Company  
Attn: Joseph M. Grana  
Post Office Box 66800  
St. Louis, Missouri 63166-6800



Re: 1631210008 -- St. Clair County  
Cerro Copper Products Company  
ILD080018914  
Compliance File

Dear Mr. Grana:

On March 24, 1993 your facility was inspected by Chris Cahnovsky of the Illinois Environmental Protection Agency. The purpose of this follow-up inspection was to determine your facility's compliance status with respect to the apparent violation cited in our November 19, 1992 Compliance Inquiry Letter. During the inspection it was determined that you have returned to compliance for the apparent violation of Section 722.134(a).

Please note, although you have returned to compliance for this apparent violation, the Agency reserves the right to pursue further enforcement.

For your information a copy of the inspection report is enclosed. Should you have any questions regarding the inspection, please contact Chris Cahnovsky at 618/346-5120.

Sincerely,

Brian S. White, Manager  
Compliance Unit  
Planning and Reporting Section  
Bureau of Land

CC: REC (cover letter only)  
JDB  
B. Novak

BSW:CNC:DV

# RCRA INSPECTION REPORT

**TYPE OF FACILITY****TYPE OF INSPECTION**

### ***NON-REGULATED STATUS***

**PART A**

**PART B PERMIT APPLICATION**

## ENFORCEMENT

## ORDERS ISSUED

**TSD FACILITY ACTIVITY SUMMARY**[illegible]

**OPERATOR**

**PERSON(S) INTERVIEWED**

**PHONE #****INSPECTION PARTICIPANT(S)****PHONE #**

**PREPARED BY**

**PHONE #**

## SUMMARY OF APPARENT VIOLATIONS

[illegible]

1631210008 - St. Clair County  
Sauget/Cerro Copper  
ILD080018914

#### REMARKS

On March 24, 1993 a reinspection was conducted at Cerro Copper Products. This inspection was a follow-up to the ~~Original~~ 1992 inspection. Present during this inspection were Chris Cahnovsky, IEPA and Joe Burroughs, Cerro Copper.

Cerro Copper has constructed a drum rack that allows the drums of hazardous waste oil to be tip on their side until they are empty. This rack will eliminate the need for 5 gallon buckets to pour off the bottom of the drum. The debris that is collected on the screen of the waste oil tank is now drummed in an open topped 55 gallon drum. This drum was properly labeled.

As a result of this inspection the violation of 722.134(a), specifically 725.273(a) and 725.273(b) have been resolved.

CNC

STATE OF ILLINOIS  
ENVIRONMENTAL PROTECTION AGENCY

SITE SKETCH

Date of Inspection: 3-24-78 Inspector: Chris H. Hickey  
Site Code: 1-1-1-1-2005 County: St. Clair  
Site Name: Green Copper Products Time: \_\_\_\_\_

4<sub>N</sub>

10 →

